


2327 Assembly

1. Fix Pole(D) to the Base(A) with Screw and Wahser(C), Using Wrench(B) provided.
3. Place Cotter Pin(E) into the hole of Pole(D).
4. Slide bearing(F) and Bushing(J) onto the Cotter Pin.
5. Slide the wire panel down the Pole, sitting on the bushing(H).
6. Slide one Busing down the Pole.
7. Insert the Sign Holder(I) into the Pole.



Part List

- A-Base(1pc)
- B-Wrench(1pc)
- C-Srew Wahser(1set)
- D-Pole(1pc)
- E-Cotter Pin(1pc)
- F-Bearing(1pc)
- G-Wire Panel(1pcs)
- H- Busing(2pcs)
- I-Sign Holder(1pc)