




SPECIALTY STORE SERVICES

454 Jarvis Ave. Des Plaines, IL 60018
PH: (800) 999-0771 | FX: (888) 368-8001
www.specialtystoreservices.com

ASSEMBLY INSTRUCTIONS

#3260 FOUR SIDED METAL PEGBOARD
FLOOR SPINNER



PARTS LIST

A - Lower Pole	1pc
B - Foot (with wheels)	5pc
C - Bolt	5pc
D - Wrench	1pc
E - Upper Pole	1pc
F - Square Frame	3pc
G - Cotter Pin	2pc
H - Bearings	2sets
I - Bushing	2pc
J - Sign Holder	1pc
K - Pegboard panel	4pc
L - Adj. Bushing	1pc

1. Attach 5 Feet (B) to the Lower Pole (A) with Bolts (C), tighten with Wrench (D).
2. Onto Lower Pole (A) Slide Adj. Bushing (L) Small end 12.75" from base washer. Tighten. Add Square Frame (F)
3. Insert one Cotter Pin(G) into the hole in Lower Pole(A), slide on one set of Bearings(H: washer, bearing, washer), one Bushing(I)(small end up), one Square Frame(F).
4. Press the button on Upper Pole(E) insert to Lower Pole(A), turn the pole till button pops out, insert one Cotter pin(G) into the Upper Pole(E), slide on one set of Bearings(H), one Bushing(I)(small end up), one Square Frame(F).
5. Hang one Pegboard Panel(K) on each side of Square Supports(F) top 2 hooks face down. Be sure all 6 hooks are attached to frame.
6. Insert the Sign Holder(J) into the Upper Pole(E)

NEED MORE HELP? CALL 800-999-0771